



Looking towards the school section
not upgraded at broken wall



Fencing covering biggest gap in
wall and collapsed pavement



Fencing covering collapsed
pavement



More collapsed pavement
and fencing



Drain cleared/installed at new
section of pavement surface
on approach to school



New surface seen from school.
Mud and debris cover pavement
at gate field exit (4.10.11)



New stretch of pavement surface
on approach to school



End of new surface at broken
wall section